

CYGNUS

Description

Cygnus is extracted in the region of Minas Gerais, Brazil. Bronze, cedar, copper and coffee hues are dominant in Cygnus's colouration, and it is spotted with ivory and black. Blocks are cut in a way to feature its depth's tridimensional effect, an extraordinary look unmatched by any other natural stone on the market.

An activator is factory-applied to darken this quartzite, and once it dissipates, its true colours will enhance the pale grey flecks present in the stone. In order to maintain a darker colouration, a sealer should be applied every 6 to 8 months or as needed.

In the course of the polishing process, an epoxy resin is applied to the surface of the stone to fill part of the stone's porosity (or pores) and natural cracks that may be apparent. This has no incident on the the durability, the maintenance or the beauty of the natural stone. It is possible that certain pores be too small to contain efficiently the resin, and reopen during the finishing stages. However, this does not affect the stone's quality or appearance. Such as it is the case with any natural stone, it is recommended to apply a sealer to extend its beauty through time.

